



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

December 8, 2004

In re Application of:  
John R. Hattersley et al.

Serial No.: 10/633,136

Filed: August 1, 2003

For: PHOSPHORESCENT OPTICAL  
SYMBOL SCANNER

Att'y Doc. No.: 562.009PA

Group Art Unit: 2876

Examiner: Allyson Neel Trail

Patent No.: 6,824,061 B1

Issued: November 30, 2004

cofc  
entered  
1/21/05  
AMW

Certificate of Corrections Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Certificate  
DEC 20 2004  
of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
FOR PTO MISTAKE [37 CFR 1.322(a)]

Sir:

1. Attached in duplicate is Form PTO-1050 with at least one copy being suitable for printing.
2. The exact page and line number where the errors occur in the application file are:

PATENT

Col. 5, line 55:

“me”

Col. 5, line 56:

“beer”

Col. 6, line 47-48:

“said diodes, herein said diodes,  
wherein”

APPLICATION FILE

Page 8, line 3:

-- the --

Page 8, line 4:

-- barrier --

Amendment Filed 06/08/04:

Page 3, line 15:

-- said diodes, wherein --

DEC 20 2004